



**NUMBER:** 08-035-16

**GROUP:** Electrical

**DATE:** March 25, 2016

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

**THE wiTECH SOFTWARE IS REQUIRED TO BE AT THE LATEST RELEASE BEFORE PERFORMING THIS PROCEDURE.**

***SUBJECT:***

Body Control Module (BCM) Re-configure

***OVERVIEW:***

This bulletin involves re-configuring the BCM.

***MODELS:***

2016 (JC) Dodge Journey

**NOTE: This bulletin applies to vehicles within the following markets/countries:  
NAFTA.**

**NOTE: This bulletin applies to vehicles built on or before December 01, 2015 (MDH 1201XX) equipped with Halogen Headlamps (Sales Code LME).**

***SYMPTOM/CONDITION:***

The customer may describe the headlamps appear more yellow than white.

***DIAGNOSIS:***

Using a scan tool (wiTECH) with the appropriate Diagnostic Procedures available in TechCONNECT, verify no DTCs are set. If DTCs are present, record them on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom/condition listed above, perform the Repair Procedure.

**REPAIR PROCEDURE:**

**NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the repair procedure.**

1. Using wiTech, determine voltage set point for low, left and right side.
2. For low beam (left or right), is the voltage set to 13.8V?
  - a. YES>>> Voltage setting is correct. No corrective action required.
  - b. NO>>> Reconfigure to 13.8V.
3. For high beam (left or right), is the voltage set to 14.2V?
  - a. YES>>> Voltage setting is correct. No corrective action required.
  - b. NO>>> Reconfigure to 14.2V.

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

Labor Operation No:	Description	Skill Category	Amount
18-19-02-BE	Module, Body Control - Reconfigure (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.

**FAILURE CODE:**

**The dealer must choose which failure code to use. If the customer came in with an issue and if the dealer finds a software update to correct that issue, use failure code CC, for all other use failure code RF.**

- If the customer's concern matches the SYMPTOM/CONDITION identified in the Service Bulletin, failure code CC is to be used.
- If an available flash is completed while addressing a different customer concern, failure code RF is to be used.

CC	Customer Concern
RF	Routine Flash