

NUMBER: 23-039-16

GROUP: Body

DATE: September 07, 2016

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 16-081. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:

Rear Shelf Panel Replacement

OVERVIEW:

This bulletin involves replacing the rear shelf panel.

MODELS:

2016 (PF) Dodge Dart

NOTE: This bulletin applies to vehicles within the following markets/countries: NAFTA.

NOTE: This bulletin applies to vehicles built on or after April 27, 2016 (MDH 0427XX) and on or before June 12, 2016 (MDH 0612XX) equipped with 9 Alpine Speakers W/Subwoofer (Sales Code RC3).

SYMPTOM/CONDITION:

The customer may describe poor rear speaker performance due to an incorrect rear shelf panel installed in the vehicle.

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. For all other customers that describe the symptom/condition listed above, perform normal diagnostics.

PARTS REQUIRED:

Qty.	Part No.	Description
1	6LN62DX9AA	Panel, Rear Shelf - Trim

23-039-16

REPAIR PROCEDURE:

1. Remove and discard the rear shelf panel. Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info>23 - Body> Interior> Panel, Rear Shelf> Removal.

-2-

2. Replace the rear shelf panel with new panel. Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info>23 - Body> Interior> Panel, Rear Shelf> Installation.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
23-20-72-97	Panel, Rear Shelf Trim - Replace (1 - Semi-Skilled)	6 - Electrical and Body Systems	0.5 Hrs.

FAILURE CODE:

ZZ Service Action
