



NUMBER: 19-002-16

GROUP: Steering

DATE: September 15, 2016

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 16-088. ALL APPLICABLE SOLD RRT VIN's HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:

Electric Power Steering Gear Noisy

OVERVIEW:

This bulletin involves replacing the electric power steering gear assembly.

MODELS:

2016 (LX) Chrysler 300

NOTE: This bulletin applies to vehicles within the following markets/countries: NAFTA.

NOTE: This bulletin applies to vehicles built on August 13, 2016 (MDH 0813XX).

SYMPTOM/CONDITION:

The customer may hear a noise coming from the steering gear.

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair.

PARTS REQUIRED:

Qty.	Part No.	Description
1	68274990AB	Electric Power Steering Gear Assembly

REPAIR PROCEDURE:

1. Replace the power steering gear assembly. Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info>19 - Steering/Gear/Removal/Installation.
2. Set the front toe alignment. Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info>02 - Front Suspension/Wheel Alignment/Standard Procedure>Front Toe.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
19-00-05-96	Electric Power Steering Unit - Replace, With Toe Alignment (2 - Skilled)	4 - Chassis	1.1 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------