GPOP - Issue Review System

Part Number: 05152029A\$

Part Description: Washer Fluid Level Sensor

Issue Prior to replacing this part due to "Low Washer Fluid" tell tale light on the dash and **Description:** the washer fluid bottle is full, please perform the this inspection.

> Inspect the sensor for a fluid coating on the sensor pins. Orange colored rain repellant can cause this fluid build-up. Clean the pins, drain the reservoir, and fill with Mopar approved washer fluid. Check to determine if the issue has been resolved. Continue with repair if necessary. Also, please inform the customer not to use Rain-X in the system to avoid this issue.

Please contact Chuck Hood at cell (248) 613-7591 if you have questions or need additional information. Thank you.

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.