

9/14/2016 MY14, 15, 16 KL

GPOP - Issue Review System

Part Number: 68194950A\$

Part Description: Dual Pane Sunroof and Sunshade Motor

Issue Description: 1. Prior to ordering this part for loss of one touch function, please re-calibrate the sunroof motor per detailed instructions in Tech Connect to see if that corrects the issue.
2. 2014 / 2015 KL: Both the sunroof and sunshade motors must be at version REV 3.0.7. Motors replaced require the same REV level to calibrate successfully. If necessary, replace both motors to match for proper calibration.

~_____
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.