

9/14/2016 MY15, 16 D2, DJ, DD, DP,

GPOP - Issue Review System

Part Number: 05086755A\$, 05086754A\$, 05015705A\$

Part Description: Rear Crank Shaft Oil Seal and Retainer Plate

Issue For Cummins equipped vehicles only;~

Description: If you are working on a 2015 or 2016 vehicle ONLY and are replacing the Rear Main Seal for oil leak, replace seal, retainer and gasket using PNs; 05086755A\$, 05086754A\$, 05015705A\$. Remove the retainer with the seal installed. Please do not disturb seal in retainer when removing from engine. Please refer to detailed repair instructions in DealerConnect TechConnect for oil seal retainer replacement.~ Cummins Engineering is currently investigating the root cause of the oil leak concern and would like to analyze these parts. Please contact Chad Eichbrecht at cell (248) 309-2695 to arrange for part return~ If you do not receive a response within 15 minutes, please proceed with normal repair.

~

~

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.