GPOP - Issue Review System

Part Number: 1UN79BD3A\$, 1UN79DX9A\$, 1UN79GT5A\$, 1UN79HL1A\$, 1UN791D3A\$,

1UN791L1A\$, 1UN791XTA\$, 1UN791X5A\$, 1UN791X9A\$, 1UP58BD3A\$, 1UP58DX9A\$, 1UP58GT5A\$, 1UP58HL1A\$, 1UP581L1A\$, 1UP581XTA\$, 1UP581X5A\$, 1UP581X9A\$, 1UQ14BD3A\$, 1UQ14DX9A\$, 1UQ141D3A\$,

1UQ141X9A\$

Part Description: Seat Shields

Issue For vehicles built prior to 5/2/2011:~

Description: Replace old shield (1UN79TRMAA) with new shield (1XN97TRMAA) and bracket (68100737AA).~

Replace old shield (1UP58TRMAA) with new shield (1XN08TRMAA) and bracket

(68100737AA).~ Replace old shield (1UQ14TRMAA) with new shield (1XN96TRMAA) and bracket (68100737AA).~

The new bracket (68100737AA) is only needed if the vehicle doesn't already have it (check PN on physical part)

~_____

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system