

8/24/2016 MY14, 15 DS

GPOP - Issue Review System

Part Number: 5RY53BD1A\$, 5RY54BD1A\$, 5RY55BD1A\$, 5RY56BD1A\$, 5RY69BD1A\$,
5RY70BD1A\$, 5RY71BD1A\$, 5RY72BD1A\$, 5RY73BD1A\$, 5RY76BD1A\$,
5RY77BD1A\$, 5RY78BD1A\$, 5RY79BD1A\$

Part Description: Foil Patch

Issue Description: If you are replacing the headliner for a 2014 or 2015 Ram 1500, you must also order patch kit PN 68315885AA to replace the foil patch for recall R47.

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
