

8/24/2016 MY16, 17 WK, WD MY17 RU

GPOP - Issue Review System

Part Number: 05048043A\$

Part Description: PSU Exhaust Phaser 05048043AB

Issue If replacing the Exhaust Phaser for the following codes:
Description: P0340 Cam Missing/Camshaft Sensor Circuit and/or
P0345 Cam Missing/Camshaft Sensor Circuit
Engineering is requesting that all three Valve Timing components (Phaser, Actuator, OCV) be replaced.~
Please label the components of which bank they came from prior to parts return.
~
Phaser 05048043AB
Actuator 05048045AB
OCV 05048044AB
Please call Joe Lovell at cell (734) 309-6467 with any questions
If a response is not received within 15 mins , then proceed with diagnostics/repair.
~
~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
