



**NUMBER:** 14-003-16  
**GROUP:** Fuel System  
**DATE:** May 28, 2016

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

**THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 16-048. ALL APPLICABLE UN-SOLD RRT VIN's HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE UN-SOLD VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. FOR VEHICLES NOT INCLUDED IN THE RRT VIN LIST, APPLICATION OF THIS SERVICE BULLETIN TO SOLD UNITS IS BASED UPON THE CUSTOMER EXPERIENCING THE SYMPTOM/CONDITIONS. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.**

**SUBJECT:**  
 Replace Fuel Pump

**OVERVIEW:**  
 This bulletin involves replacing the fuel pump module.

**MODELS:**  
 2015 (BU) Jeep Renegade

**NOTE: This bulletin applies to vehicles within the following markets/countries: NAFTA and EMEA.**

**NOTE: This bulletin applies to vehicles built on or before April 10, 2015 (MDH 0410XX) equipped with 2.4L I4 Multiair Engine (Sales Codes ED6).**

**SYMPTOM/CONDITION:**  
 Some vehicles may have been built with a fuel pump that can cause a no start condition on vehicles with low mileage (Usually less than 100 miles).

**DIAGNOSIS:**  
 If the vehicle is unsold and the VIN is listed in VIP or your RRT VIN list, perform the repair.

**PARTS REQUIRED:**

Qty.	Part No.	Description
1	68254869AA	Module, Fuel Pump
1	68079799AA	O-ring

**REPAIR PROCEDURE:**

1. Replace the fuel pump module. Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info>14 - Fuel System/Fuel Delivery/Module, Fuel Pump/Removal and Installation>2.4L.

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

Labor Operation No:	Description	Skill Category	Amount
14-50-01-9B	Module, Fuel Pump - Replace (2 - Skilled)	1 - Engine Repair and Performance	0.6 Hrs.

**FAILURE CODE:**

ZZ	Service Action
----	----------------