



Service Bulletin

File in Section: -

Bulletin No.: 16-NA-018

Date: January, 2016

TECHNICAL

Subject: Intermittent Airbag Indicator Light ON with Communication DTCs Set

Attention: This Bulletin also applies to any of the models that may be Export vehicles.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Malibu	2014	2015			All	All

Condition	Some customers may comment that the airbag light is ON, and technicians may find Communication DTCs set.
Cause	The supplemental restraint wiring harness may be pinched under the passenger seat track.

Correction

Repair damaged wiring as necessary.

Service Procedure

1. Remove the passenger seat and inspect the wiring harness. Refer to *Driver or Passenger Seat Removal and Installation* in SI.
2. Repair wiring as necessary. Refer to *SIR/SRS Wiring Repairs* in SI.

Warranty Information

Labor Operation	Description	Labor Time
5430902	Wire-to-Wire Repair	Use Published Labor Operation Time

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION