

**15236 – Special Coverage Adjustment - Resistance Wire Heated Seat Spot Burn Holes**

Updated Date: Jan 13, 2016 14:20 ET

GM CUSTOMER CARE AND AFTERSALES

DCS3889

URGENT - DISTRIBUTE IMMEDIATELY

Date: January 13, 2016

Subject: 15236 – Special Coverage Adjustment
Resistance Wire Heated Seat Spot Burn HolesModels: 2006 Chevrolet Equinox
2006 Pontiac Torrent

To: All General Motors Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New or Used Vehicle Sales Manager, and Warranty Administrator

General Motors is releasing Special Coverage Adjustment 15236 today. The total number of U.S. vehicles involved is approximately 4,400. Please see the attached bulletin for details.

Customer Letter Mailing

The customer letter mailing will begin on January 25, 2016.

Global Connect (GWM)

The "Investigate Vehicle History" (IVH) screen was updated January 13, 2016.

-

Campaign Initiation Detail Report (CIDR)

The CIDR is not available for Special Coverage Adjustments.

GM CUSTOMER CARE AND AFTERSALES

15236 Bulletin.pdf

About this Article

Reference Number: GCUS-9-1506
Published to: Service
Version: 1.0
Original Published Date: Jan 13, 2016 14:20 ET
Expires: Feb 12, 2016 0:00 ET
Contact: Loren.Rusk@gm.com