



15236A – Special Coverage Adjustment Revised - Resistance Wire Heated Seat Spot Burn Holes

Updated Date: Jan 19, 2016 15:45 ET

GM CUSTOMER CARE AND AFTERSALES

DCS3897

URGENT - DISTRIBUTE IMMEDIATELY

Date: January 19, 2016

Subject: 15236A – Special Coverage Adjustment Revised
Resistance Wire Heated Seat Spot Burn Holes

Models: 2006 Chevrolet Equinox
2006 Pontiac Torrent

To: All General Motors Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New or Used Vehicle Sales Manager, and Warranty Administrator

This bulletin is being revised with additional ordering information in the Parts Information section. Please discard all copies of Special Coverage Bulletin 15236.

GM CUSTOMER CARE AND AFTERSALES

15236A Bulletin.pdf

About this Article

Reference Number: GCUS-9-1529
Published to: Service
Version: 1.0
Original Published Date: Jan 19, 2016 15:45 ET
Expires: Feb 18, 2016 0:00 ET
Contact: Loren.Rusk@gm.com