

**15671- Service Update - Excessive Wiring Harness Length**

Updated Date: Jan 15, 2016 9:35 ET

GM CUSTOMER CARE AND AFTERSALES

DCS3894

URGENT - DISTRIBUTE IMMEDIATELY

Date: January 15, 2016

Subject: 15671 – Service Update Bulletin  
Excessive Wiring Harness LengthModels: 2015 Chevrolet Colorado  
2015 GMC Canyon  
Equipped with 3.6L V6 Engine (RPO LFX)

To: All Chevrolet and GMC Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and  
Service Director, Parts Manager, New Vehicle Sales Manager, and Warranty Administrator

General Motors is releasing Service Update Bulletin 15671 today. The total number of U.S. vehicles involved is 64,366. Please see the attached bulletin for details.

Global Warranty Management (GWM)

The "Investigate Vehicle History" (IVH) screen will be updated January 15, 2016. A list of involved vehicles in dealer inventory is attached to this message.

GM CUSTOMER CARE AND AFTERSALES



15671 Bulletin.pdf



15671 US BAC stock list.xlsx

**About this Alert**

---

Reference Number: GCUS-3-405

Published to: Home Page

Version: 1.0

Alert Type: Service Update

Original Published Date: Jan 15, 2016 9:35 ET

Expires: Mar 15, 2016 0:00 ET

Contact : loren.rusk@gm.com