



# Service Bulletin

## INFORMATION

**Subject:** Radio Display May Momentarily Flicker When Vehicle Is First Started

**Models:** 2015 Chevrolet Silverado 1500, Silverado 2500/3500 (RPO AVF), Suburban (RPO AVF), Tahoe (RPO AVF)  
2015 GMC Sierra 1500, Sierra 2500/3500 (RPO AVF), Yukon models (RPO AVF)  
2016 Chevrolet Silverado, Suburban, Tahoe  
2016 GMC Sierra, Yukon  
**ATTENTION: Only Vehicles Equipped with Rear Seat Entertainment RPO U42**

*This PI was superseded to update the Models, Concern/Condition, and Recommendations/Instructions. Please discard PIT5378B.*

### Condition/Concern

Some customers may comment that the radio display flickers momentarily when first starting the vehicle.

### Recommendation/Instructions

Please reprogram the Radio Controls with the latest calibrations in TIS2WEB.

### Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
2810325	Radio Control Reprogramming with SPS	Use Published Labor Operation Time

### Additional SI Keywords

Flash, Roll, overlap,

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION