

SB-10058978-2246

GPOP - Issue Review System

Part Number: 68258392A\$, 68258395A\$, 68258396A\$, 68261015A\$, 68258195A\$, 68258196A\$

Part Description: RA3/RA4 Radio

Issue Description: The MY16 RA3/4 radios are susceptible to randomly set an erroneously BCM or IPC "U0184 - Loss of Com with Radio" fault. The radio should not be replaced for this issue if the fault is stored, if the code cannot be reproduced and no trouble can be found (radio functions properly). In this case it is no impact to the customer in any way. Do NOT replace the radio for this issue. Please contact John Carlesimo at cell (248) 941-8756 if you have any further questions regarding this fault.

~ _____ ~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
