

3/23/2016 MY15 JK, MK

GPOP - Issue Review System

Part Number: 05149171A\$

Part Description: Oxygen Sensor

Issue Description: Before replacing the Upstream (1/1) O2 Sensor on a 2.4L MK due to a P0131 fault code, please contact Vijay Thiruvengkatachary at cell (906) 281-8495.~

Before replacing the Left Downstream (2/2) O2 Sensor on a 3.6L JK due to a P0157 fault code, please call Jerry Tomlin at cell (248) 202-5329. ~

Engineering would like determine whether the sensor has been contaminated with oil.~

If no response is received within 15 minutes, then continue with repair.
For all other fault codes, please perform the applicable diagnostic routine.~

~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.