

New Bonneville Cylinder Head Oil Residue



Notice Information

Posted Date: 2/25/2016 10:45:42 AM
Posted To: Dealer Principal, Service / Technical
Subject: Service/Technical

TOL NOTICE (US&CAN) – February 25, 2016

New Bonneville Cylinder Head Oil Residue

It has been reported that there may be instances of excess oil visible around the cylinder head bolts on the new Bonneville series engines (Street Twin, Bonneville T120, Thruxton). This excess oil residue may appear to be an oil leak, as shown in the photos below.



Please be assured this is not a fault or the result of an oil leak, rather it is a small amount of excess oil that can become trapped around the cylinder head bolts during assembly. When the engine is heated, the trapped oil may then seep out. If this oil spotting is observed, thoroughly clean the area using a proprietary degreaser and run the engine again, monitoring the area to ensure oil seepage stops.

Contact Triumph 24/7 Customer Support at (888) 284-6288 if you have any questions.

