

Service Bulletin

16-030

March 23, 2016 03508 Version 1

Service Manual Update: DTC B121E

AFFECTED VEHICLES

Year	Model	Trim	VIN Range
2016	Pilot	ALL	ALL

BACKGROUND

The service information is missing the troubleshooting procedures for DTC B121E (climate control unit lost communication with touch control panel). DTC B121E was mistakenly assigned to this vehicle and does not apply. For troubleshooting, use the procedures for DTC U0180 (lost communication with automatic lighting control unit/sensor).

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.