



Service Bulletin

INFORMATION

Subject: Engineering Information – Service Side Detection System Message Displayed and/or DTCs B101D, U0232 and/or U0233 Set

Models: 2013-2014 Chevrolet Cruze
Equipped with Side Obstacle Detection (RPO UFT)

This PI has been revised to end the need for information from the field. Please discard PIE0346.

If you encounter a vehicle with this concern, please refer to SI diagnostics.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION