



Service Bulletin

INFORMATION

Subject: Clunk Or Rattle Noise From Steering Over Bumps

Models: 2015 Chevrolet Colorado
2015 GMC Canyon

Condition/Concern

The customer may state there is a rattle or clunk noise from the front of vehicle over bumps. The technician may isolate this noise to the lower steering intermediate shaft.

Recommendation/Instructions

Engineering is aware of the concern and is currently working on a resolution. This PI will be revised once a fix becomes available.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION