



# Service Bulletin

File in Section: -

Bulletin No.: 16-NA-105

Date: April, 2016

## INFORMATION

**Subject: Diagnostic Tip DTC U184A - Lost Communication with Body Control Module (BCM)**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado LD Crew Cab	2016	2016				
GMC	Sierra LD Crew Cab	2016	2016				

<b>Condition</b>	Some technicians may find DTC U184A - Lost Communication with Body Control Module (BCM) set or stored in history.
<b>Cause</b>	This condition may be due to a false setting of the DTC.
<b>Additional Options</b>	Equipped with HYBRID PROPULSION-ELECTRIC, PARALLEL, 10KW CONTINUOUS POWER (RPO HP5)

### Correction

Technicians are to clear and ignore this DTC unless the Engine Control Module (ECM), Transmission Control Module (TCM) or Generator Control Module (GCM) have U codes set indicating a loss of communications with the BCM.

<b>Version</b>	1
<b>Modified</b>	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION