



Service Bulletin

File in Section: -

Bulletin No.: 16-NA-125

Date: April, 2016

TECHNICAL

Subject: Front Propeller Shaft Broken

Attention: This Bulletin applies to any of the models that may be Export vehicles.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet GMC	All 4WD Heavy Duty Trucks	2011	2016			All	All

Condition	Some technicians may notice a broken propeller shaft or U-joint due to different causes.
------------------	--

Correction

If you encounter a vehicle with a broken propeller shaft or U-joint, replace the propeller shaft by referring to the proper procedures in SI.

General Motors has released a new propeller shaft with a stronger steel tube and larger U-joint.

Parts Information

Description	Part Number	Qty
SHAFT ASM-F/AXL PROP	84016569	1

Warranty Information

Labor Operation	Description	Labor Time
3020280	Front Propeller Shaft Replacement	Use Published Labor Operation Time

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION