



Service Bulletin

INFORMATION

Subject: 2016 6.6L Duramax Engine Control Module Parts Restriction Has Ended

Models: 2016 Chevrolet Silverado, Express
2016 GMC Sierra, Savana
Equipped with the 6.6L Duramax Engine - RPO LML/LGH

This PI was superseded to update Part Restriction. Please discard PIP5333.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

The PQC Parts Restriction has ended on 2016 6.6L Duramax, RPO LML/LGH, Engine Control Module, P/N 12662677.

Parts can now be ordered through the regular CCA parts process.

Recommendation/Instructions

GM Engineering would like to thank all dealers that participated in this parts restriction.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION