



Service Bulletin

File in Section: 08 - Body and Accessories

Bulletin No.: 15-08-42-001A

Date: May, 2016

INFORMATION

Subject: Exterior Lighting Components “Tinted or Smoked” by an Outside Vendor

Models: 2017 and Prior GM Passenger Cars and Light Duty Trucks

Attention: This Bulletin also applies to any of the above models that may be Export from North America vehicles.

This Bulletin has been revised to add the 2017 Model Year. Please discard Corporate Bulletin Number 15-08-42-001.

Some customers may comment that the replacement exterior lighting component does not match the opposite side component.

This may be due the customer having an outside vendor tint or smoke the exterior lighting lens.

Original Equipment



4070546

“Tinted or Smoked” Lens



4070548

Original Equipment



4070549

Original Equipment



4080642

“Tinted or Smoked” Lens



4070550

“Tinted or Smoked” Lens



4080643

GM's Position on Altering Exterior Lighting Components

General Motors does not recommend or endorse "tinted/smoked" headlamps, tail lamps or other exterior lighting components. These components are engineered specifically to comply with applicable laws and regulations, including Federal Motor Vehicle Safety Standards, and should not be altered.

Parts that have been altered, modified or tampered with are not covered under warranty. Please refer to Policy & Procedures Manual Section 1.2.2.2 - Damage Due to Accidents, Misuse, or Alterations.

Altered, modified or tampered with parts will be subject to debit.

