



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** SES Light with DTC: P0AE3

**Models:** 2016-2017 Chevrolet Volt

*This PI was superseded to update Recommendation/Instructions. Please discard PIC6165A.*

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

Some customers may experience a SES lamp with a history or current DTC: P0AE3.

### Recommendation/Instructions

GM engineering has released updated software to address this concern.

If you experience this concern, update the K114B HPCM2 with the latest calibration available in TIS-2-Web.

**Note:** If there are any other DTCs in the vehicle, record the DTC's and any related freeze frame data before installing this calibration and diagnosis those DTC's first.

### Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
2810265	Hybrid Powertrain Control Module 2 Reprogramming with SPS	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION