



Service Bulletin

PRELIMINARY INFORMATION

Subject: SES Lamp With DTC P015A

Models: 2012-2016 Chevrolet Equinox
2012-2016 GMC Terrain
2013-2016 Buick Verano
2013-2016 Cadillac ATS
2013-2016 Chevrolet Malibu
2014-2016 Chevrolet Impala
2015-2016 Chevrolet Colorado
2015-2016 GMC Canyon
Equipped with engine 2.4L LEA, 2.5L LCV and 2.5L LKW

This PI was superseded to update model years. Please discard PIP5389.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A customer may comment on an SES light with DTC P015A set.

Recommendation/Instructions

If SI diagnostics have been completed and a repair has not been established, inspect the engine oil level for being overfilled.

If the engine oil level is found to be overfilled, readjust to correct level and re-evaluate the concern.

If the DTC is still setting, inquire if the customer is utilizing the transmission manual / tap shift feature and record this information on the repair order.

At this time advise the customer that engineering is aware of this concern and is working on a repair.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION