

6/15/2016 MY15 - 16 JK

GPOP - Issue Review System

Part Number: 68241067A\$, 68219832A\$

Part Description: TPM Sensor or Control Module

Issue Description: 2015 and 2016 JK vehicles only - Engineering is investigating a Tire Pressure Monitor (TPM) issue for TPM lamp ON.~

Prior to replacing any components (Sensor or TPM Control Module) on MY15 or 16 JK vehicles, please contact Raja Charabuddi on cell (248) 202-7313. If no response within 15 minutes, proceed with repair.

~

~

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.