



Service Bulletin

PRELIMINARY INFORMATION

Subject: DTC P0133 or P1133

Models: 2010 Chevrolet Equinox
2010 GMC Terrain
Equipped with 3.0 LF1

This PI was superseded to update Model Years. Please discard PIP4699.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

One of the above vehicles may come in with an SES light on and have a DTC P0133 and/or P1133.

Recommendation/Instructions

Check for the post and pre oxygen sensor connectors being swapped.

The pre sensor connected to post connector and post sensor connected to pre connector.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION