

# Technical product information

|                 |                                                |
|-----------------|------------------------------------------------|
| Topic           | PDI rear door sunblind initialisation          |
| Market area     | Bentley: worldwide (2WBE),Hongkong-Macau (5HK) |
| Brand           | Bentley                                        |
| Transaction No. | 2044880/1                                      |
| Level           | EH                                             |
| Status          | Approval                                       |
| Release date    |                                                |

## New customer code

| Object of complaint                                                                     | Complaint type                             | Position |
|-----------------------------------------------------------------------------------------|--------------------------------------------|----------|
| Body fixtures and fittings -> Sunblind operation -> Electrically raise side glass blind | functionality -> without function / defect |          |

## New workshop code

| Object of complaint                                                     | Complaint type                          | Position |
|-------------------------------------------------------------------------|-----------------------------------------|----------|
| Body fixtures and fittings -> Doors, closures -> Rear-door control unit | control units, services -> code missing | left     |
| Body fixtures and fittings -> Doors, closures -> Rear-door control unit | control units, services -> code missing | right    |

# Vehicle data

## Bentayga

### Sales types

| Type | MY   | Brand | Designation | Engine code | Gearbox code | Final drive code |
|------|------|-------|-------------|-------------|--------------|------------------|
| 4V1* | 2017 | E     |             | *           | *            | *                |

# Documents

| Document name              |
|----------------------------|
| <a href="#">master.xml</a> |



Customer statement / workshop findings

Rear door sunblind inoperative

Technical background

PDI process

Production change

.

Measure

Ensure any PDI check sheet is printed on the day of the PDI from a terminal connected to a live online workshop manual and that all PDI procedures on that check sheet specific for the individual car are performed. See example below

|    |                                                                                                                                        |  |  |  |
|----|----------------------------------------------------------------------------------------------------------------------------------------|--|--|--|
| 33 | Check the initialisation of the sunblinds. Refer to "Rear door sunblind – to remove and fit" for initialisation process.<br>Rep.-Gr.70 |  |  |  |
|----|----------------------------------------------------------------------------------------------------------------------------------------|--|--|--|