



# Service Bulletin

File in Section: -

Bulletin No.: 16-NA-177

Date: June, 2016

## INFORMATION

**Subject:** Front View Camera Module - History DTC U0121

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	XT5	2017	2017			All	All

<b>Involved Region or Country</b>	North America
<b>Condition</b>	Front View Camera Module DTC U0121 in history
<b>Cause</b>	Software anomaly

### Correction

Technicians may find a history DTC U0121 in the Front View Camera Module when checking DTCs.

Ignore this code as it causes no customer concern or vehicle issue.

This code will be eliminated in the 2018 model year.

<b>Version</b>	1
<b>Modified</b>	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION