



Service Bulletin

File in Section: -

Bulletin No.: 16-NA-184

Date: June, 2016

TECHNICAL

Subject: Front Seat Back Recliner Handle is Broken

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Colorado	2015	2016	SOP	April 18, 2016	All	All
GMC	Canyon	2015	2016	SOP	April 18, 2016	All	All

Involved Region or Country	North America
Condition	Some customers may comment that the front seat recliner handle is broken.

Correction

If you encounter a vehicle with the above concern, replace the handle with the newly designed part. Refer to *Front Seat Back Recliner Handle Replacement* in SI.

Parts Information

Description	Part Number	Color/Side
HANDLE-F/SEAT RECL	84021551	Black/ LH Side
HANDLE-F/SEAT RECL	84021552	Black/ RH Side
HANDLE-F/SEAT RECL	84021553	Cocoa/ LH Side
HANDLE-F/SEAT RECL	84021554	Cocoa/ RH Side

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
7020700	Front Seat Back Recliner Handle Replacement	Use Published Labor Operation Time

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION