



Service Bulletin

File in Section: -

Bulletin No.: 16-NA-187

Date: June, 2016

TECHNICAL

Subject: Exterior Approach Lighting Flashes Intermittently Causing Battery Rundown

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	CT6	2016	2016			All	All

Involved Region or Country	North America
Condition	Some customers may comment that the exterior approach lighting flashes intermittently, causing a low battery.
Cause	This may be caused by the Keyless Entry Control Module (KECM) intermittently detecting a transmitter on the perimeter of exterior coverage and flashes approach lighting, discharging the battery.

Correction

If you encounter a vehicle with the above concern, reprogram the keyless entry control module with the latest calibrations. Refer to *Keyless Entry Control Module Programming and Setup* in SI.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2810545	Keyless Entry Control Module Reprogramming with SPS	Use Published Labor Operation Time

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION