

Service Bulletin

Bulletin No.:

n No.: 16-NA-190 Date: August, 2016

TECHNICAL

Subject: Radio Volume and Tune Knobs Broken, Missing or Will Not Stay Attached


Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
Branu.	woder.	from	to	from	to		
Chevrolet	Impala (VIN 1)	2014	2016			All	All
Chevrolet	Impala	2017	2017				

Involved Region or Country	NORTH AMERICA, MIDDLE EAST, KOREA, ISRAEL		
Additional Options (RPO)	Equipped with Radio RPOs - IO3, IO5 or IO6		
Condition	Some customers may comment the Volume and/or Tune knob is broken, missing or will not stay attached to the control assembly.		
Cause	The cause of the condition may be improper retention of the original knobs, which can be removed.		

Correction

Important: DO NOT replace the entire control assembly for this concern.

Replace the affected Volume and/or Tune knob(s) with service kit listed in the parts table below.



Parts Information

Description	Part Number	Qty
KNOB KIT, RDO CONT	84175369	1

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
3480268*	Volume and/or Tune Knob Replacement	0.2 hr
*This is a unique Labor Operation for Bulletin use only.		

4533361

Copyright 2016 General Motors LLC. All Rights Reserved.

Version	2
Modified	August 16, 2016 – Added Radio RPO - IO3.

GM bulletins are intended for use by professional technicians, NOT a "<u>do-it-yourselfer</u>". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, <u>DO NOT</u> assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION