



Service Bulletin

File in Section: -

Bulletin No.: 16-NA-255

Date: August, 2016

TECHNICAL

Subject: Damage to Matte Black Decal on Rear Compartment Lid When Installing Black or Illuminated Bow Tie Kit

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Camaro	2017	2017			All	All

Involved Region or Country	North America and N.A. Export Regions
Additional Options (RPO)	Equipped with 50th Anniversary appearance package (RPO H50) and Black Finish Bow Tie (RPO RIK) or Illuminated Bow Tie (RPO R88)
Condition	Some technicians may comment that during the removal of the rear compartment lid emblem for the install of the illuminated or black emblem, some adhesive/residue is still present on the decal.

Correction

If you encounter a vehicle with the above concern, and the adhesive/residue is unable to be removed, replace the rear compartment lid decal.

Important: The use of adhesive cleaners on the matte black decal will alter the finish.

Parts Information

Description	Part Number	Application
DECAL-R/CMPT LID LWR	23280409	Coupe
DECAL-R/CMPT LID LWR	23280410	Convertible

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
1480708*	Replace Rear Compartment Lid Decal	0.7 hr
*This is a unique Labor Operation for Bulletin use only.		

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION