



Service Bulletin

File in Section: -

Bulletin No.: 16-NA-279

Date: September, 2016

TECHNICAL

Subject: Brake Lights Stay Illuminated Without Brake Pedal Being Applied

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Malibu	2014	2015				
	Malibu (VIN 1)	2016	2016				

Involved Region or Country	North America and Israel
Condition	Some customers may comment that the brake lights stay illuminated without the brake pedal applied.

Correction

If you encounter a vehicle which is exhibiting this condition, a revised software calibration has been released to address this condition.

Service Procedure

Reprogram the Body Control Module (BCM) with the latest calibration available. Refer to *Body Control Module Programming and Setup* in SI.

Warranty Information

Labor Operation	Description	Labor Time
2810215	Body Control Module Reprogramming with SPS	Use Published Labor Operation Time

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

Copyright 2016 General Motors LLC. All Rights Reserved.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION