



Bulletin No.: PIE0363A

Date: 24-Aug-2016

Service Bulletin

INFORMATION

Subject: Engineering Information – Rear Bumper Step Pad Melted or Warped

Models: 2015-2016 Chevrolet Silverado

2015-2016 GMC Sierra

Equipped with Diesel Engine (LML) or Gas Engine (L96) with Assist Corner Steps (BWN)

This PI has been revised to end the need for information from the field. Please discard PIE0363.

If you encounter a vehicle with the concern, please refer to SI diagnostics.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION