



Service Bulletin

INFORMATION

Subject: Engineering Information – USB Receptacle Inoperative

Models: 2016 Buick LaCrosse, Regal
2016 Cadillac ATS, CT6, CTS, Escalade Models, SRX, XTS
2016 Chevrolet Camaro, Colorado, Corvette, Cruze, Impala, Malibu, Silverado, Suburban, Tahoe
2016-2017 Chevrolet Volt
2016 GMC Canyon, Sierra, Yukon
Equipped with Radios IO5 or IO6

This PI has been revised to end the need for information from the field. Please discard PIE0365.

If you encounter a vehicle with this concern, please refer to Bulletin Number 16-NA-242.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION