

Bulletin No.: PIE0374

Date: 11-Aug-2016

# Service Bulletin

## INFORMATION

Subject: Engineering Information – Engine No Crank / No Start Due to a Discharged Battery

Attention:

Proceed with this EI ONLY if the customer has commented about this concern AND the PIE number is listed in the Global Warranty Management / Investigate History link (GWM/IVH). If the customer has not commented about this condition or the EI does not show in GWM/IVH, disregard the PI and proceed with diagnostics found in published service information. THIS IS NOT A RECALL — refer to the latest version of Service Bulletin 04-00-89-053 for more details on the use of Engineering Information bulletins.

Brand:	Model:	Mode	l Year:	VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	CT6	2016	2016			All	All

Involved Region or Country	North America
Condition	Important: If the customer did not bring their vehicle in for this concern, DO NOT proceed with this EI.  Some customers may comment on a vehicle no start due to a drained battery.  During diagnosis a technician may find low voltage and loss of communication DTCs.
Cause	GM Engineering is attempting to determine the root cause of the above condition. Engineering has a need to gather information on vehicles PRIOR to repair that may exhibit this condition. As a result, this information will be used to "root cause" the customer's concern and develop/validate a field fix.

#### Correction

If you encounter a vehicle with the above concern, do NOT disconnect the battery.

Verify the state of charge with a multi-meter and connect the EL-50313 Midtronics® GR8 Battery Charger/Tester and contact the engineer listed below with the findings.

#### **Contact Information**

Engineer Name	Phone Number	
Mick Dowd	248-804-0398	

Please include the following information if leaving a message:

- Technician name
- Dealer name and phone number

Complete VIN and repair order (R.O) number

On the repair order, document the date and time the call was placed (even if the engineer was not reached).

If engineering is unable to return the call within one hour, proceed with diagnosis and repair based on information found in SI.

### **Warranty Information**

Modified

If engineer was contacted or required information was provided, use:

Labor Operation	Description	Labor Time
4081268*	Engineering Information — Engine No Crank / No Start Due to a Discharged Battery	0.4 hr
*This is a unique Labor Operation for Bulletin use only. It will not be published in the Labor Time Guide		

Version	1

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

