



Service Bulletin

PRELIMINARY INFORMATION

Subject: Power Steering Hose Clamp Usage

Models: 2008-2009 Chevrolet Impala

This PI was superseded to update Recommendation/Instructions. Please discard PIC5101.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A customer may comment of fluid leaks from under the engine compartment.

Recommendation/Instructions

In cases of power steering system repairs where diagnosis leads to a steering hose clamp replacement, replace with clamp currently listed in electronic parts catalog.

General Motors does not recommend gear type clamps for this application.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION