

**Title**

2016 CX-9 - NEW IDS VERSION 101.02 ALLOWS TPMS INITIALIZATION USING M-MDS

**Content**

Version 101.02 of the IDS software has been updated to allow the TPMS initialization procedure to be performed on 2016 CX-9 with M-MDS.

With the previous IDS version, an error message ("The operation has been unsuccessful") appeared when performing TPMS initialization. This was caused by improper IDS software.