

Subject		Market
Fuel Door Will Not Open Due To Detached Cable		USA
Service Category	Section	
Vehicle Exterior	Door/Hatch	
Applicability		
16MY iA		

APPLICABLE VEHICLES

2016	iA
------	----

CONDITION

Fuel door will not open when pulling the release lever because fuel door cable has detached from the retainer.


RECOMMENDATIONS

This issue is currently under investigation.

- Please create a TAS case and contact Technical Assistance (TAS) to submit details on any vehicle identified matching the condition described in this document prior to repair.
- If you are attempting to contact TAS on a weekend or TMS holiday, continue with diagnosis and submit the requested information on the next available work day. Retain all replaced parts and technician notes for possible review with TMS TAS Product Engineer.

LINK REFERENCES

This Tech Tip does not contain any link references