



# Technical Journal

TITLE:  
**Fender flares, poor fit**

<b>REF NO:</b> TJ 31446	<b>ISSUING DEPARTMENT:</b> Technical Service	<b>CAR MARKET:</b> United States and Canada	
<b>PARTNER:</b> 3 US 7510 Volvo Car USA		<b>ISSUE DATE:</b> 2016-04-19	<b>STATUS DATE:</b> 2016-04-22
<b>FUNC GROUP:</b> 8259	<b>FUNC DESC:</b> Miscellaneous	Page 1 of 3	

“Right first time in Time”

## Attachment

File Name	File Size
TJ31446.jpg	0.1079 MB

## Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
137							2016-2016		0000019-9999999	201524-201608
157							2015-2016		0000022-9999999	201450-201605

## CSC Customer Symptom Codes

Code	Description
M3	Exterior trim/components/Moldings, trim loose
M4	Exterior trim/components/Moldings, trim poorly aligned or fit
M5	Exterior trim/components/Other trim problems

## VST Operation Number

## DTC Diagnostic Trouble Codes



## Text

### DESCRIPTION:

The front and rear fender flares may have poor fit. Improvements have been implemented on parts from structure weeks above.

If a failure occurs after the breakpoint, please report back on which fender flare, and where the location of the failure is. See attached guideline to judge the failure.

### SERVICE:


Replace the fender flare according to VIDA. If a failure may occur on vehicles after above structure weeks, document the failure mode before the repair is done.

Add relevant information like comments and photos that describe the location of the failure. Take photos from different views.

### VEHICLE REPORT:

Yes, please submit a Vehicle Report if failure occurs after the structure weeks or if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8259.

**To view TJ attachment continue to next page. This TJ has one attachment.**



TJ 31446