



Technical Journal

TITLE:

Outer rear view mirrors, folding/noise issue

REF NO: TJ 30914	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Cars North America		ISSUE DATE: 2016-04-20	STATUS DATE: 2016-04-28
FUNC GROUP: 8460	FUNC DESC: Outside mirrors	Page 1 of 2	

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
134							2011-2016		0000194-0400799	201020-201537
137							2016-2016		0000019-0000586	201524-201537
138							2016-2016		0000122-0098000	201521-201537
155							2015-2016		0001147-0298568	201035-201537
157							2015-2016		0000022-0008836	201450-201537

CSC Customer Symptom Codes

Code	Description
XP	Door mirrors/Folding does not work
3H	Door mirrors/Noise when folding

VST Operation Number

VST Operation Number	Description
84622-2	Sidemirror complete replace

DTC Diagnostic Trouble Codes

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.



Text

DESCRIPTION:

*VST Operation NO 36004-2,36002-3 are excluded.

Customer may experience that the function folding outer rear view mirror do not work and a noise is present when locking/unlocking vehicle.

SERVICE:

*In case of customer complaints replace affected ORVM (outer rear view mirror) according to VIDA.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support Not Needed", use function group 8460.