



Technical Journal

TITLE:

Fresh air hose loose from air filter housing

REF NO:
TJ 31913.1.0

ISSUING DEPARTMENT:
Technical Service

CAR MARKET:
United States and Canada

PARTNER:
3 US 7510 Volvo Car USA

ISSUE DATE:
2016-09-22

STATUS DATE:
2016-09-28

FUNC GROUP:
8530

FUNC DESC:
Rear seat, passenger seat, bench

Page 1 of 3

“Right first time in Time”

Attachment

File Name	File Size
31913.pdf	0.2550 MB

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
256							2016-2016		0000561-0079653	201505-201609

CSC Customer Symptom Codes

Code	Description
ZO	Rear seat/Squeak/rattle

VST Operation Number

VST Operation Number	Description
99400-2	General reimbursement acc. to TJ/QB

DTC Diagnostic Trouble Codes

Text

**DESCRIPTION:**

Customer may experience a noise in second row seat while driving. This applies only for 7-seated cars.



SERVICE:

Remove all 6 end caps as described in attached picture.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8530.

To view TJ attachment continue to next page. This TJ has one attachment.



31913