



Technical Journal

TITLE:

Fender flares, poor fit

REF NO: TJ 31446.1.1	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2016-09-22	STATUS DATE: 2016-09-28
FUNC GROUP: 8259	FUNC DESC: Miscellaneous	Page 1 of 3	

“Right first time in Time”

Attachment

File Name	File Size
TJ31446.jpg	0.1079 MB

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
137							2016-2016		0000019-9999999	201524-999952
157							2015-2016		0000022-9999999	201450-999952

CSC Customer Symptom Codes

Code	Description
M3	Exterior trim/components/Moldings, trim loose
M4	Exterior trim/components/Moldings, trim poorly aligned or fit
M5	Exterior trim/components/Other trim problems

VST Operation Number

DTC Diagnostic Trouble Codes

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.



Text

DESCRIPTION:

The front and rear fender flares may have poor fit. Improvements have been implemented on parts from structure week 16w05-> for V60CC and 16w08-> for S60CC .

If a failure occurs after the breakpoint, please report back on which fender flare, and where the location of the failure is. See attached guideline to judge the failure.

SERVICE:

Replace the fender flare according to VIDA. If a failure may occurs on vehicles after above structure weeks, document the failure mode before the repair is done.

Add relevant information like comments and photos that describe the location of the failure. Take photos from different views.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if failure occur after the structure weeks or if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8259.

To view TJ attachment continue to next page. This TJ has one attachment.

