

[Next Unread Message](#)

[View Message](#)

Sent on	03	01	2016	Expires on	03	18	2016
From	Motorcycle National Field Service						
Subject	RECALL INFORMATION UPDATE: Service Bulletin NSS300 #2						

Re: S/B NSS300 #2 – 2014 NSS300/A Rear Brake Line Joint Torque

Dear Honda Powersports Dealer,

Contrary to the initial “affected units” information published, not every model year 2014 NSS300/A is affected by this recall.

AFFECTED UNITS
2014 NSS300: ML [REDACTED] *E5 [REDACTED] thru ML [REDACTED] *E5 [REDACTED]
2014 NSS300A: ML [REDACTED] *E5 [REDACTED] thru ML [REDACTED] *E5 [REDACTED]

* Denotes check digit

REVISED SERVICE BULLETIN
Service Bulletin NSS300 #2 has been revised to include the affected VIN range of each model. Revised information is indicated by a NEW bar adjacent to the text. Please destroy all printed copies of the original Service Bulletin and circulate the revised bulletin to all affected departments.

Make sure all departments in your dealership are aware of this action.

Thank you,
American Honda Motor, Co., Inc.

Bradley Little
Manager, National Field Service
Motorcycle Division

Bulletin Number: 16-0062