

Safety Recall: Takata Driver's Airbag Inflator

AFFECTED VEHICLES

Year	Model	Trim	VIN Range
2013–16	ILX	ALL	Check the iN VIN status for eligibility
2013–14	ILX Hybrid	ALL	Check the iN VIN status for eligibility
2007–16	RDX	ALL	Check the iN VIN status for eligibility
2005–12	RL	ALL	Check the iN VIN status for eligibility
2009–14	TL	ALL	Check the iN VIN status for eligibility
2010–13	ZDX	ALL	Check the iN VIN status for eligibility

BACKGROUND

In certain vehicles, the driver's (front) airbag inflator could produce excessive internal pressure during airbag deployment. If an affected airbag deploys, the increased internal pressure may cause the inflator casing to rupture. Metal fragments could pass through the airbag cushion material, possibly causing injury or fatality to vehicle occupants.

A preliminary list of affected vehicles is available and you can identify any vehicles by performing an iN VIN status inquiry. The final list of affected vehicles may change. All affected vehicles are on stop sale and cannot be sold until the inflator is repaired with a counter-measured part. Replacement parts are currently not available.

This bulletin will be revised once repair information, warranty claim information, and part information and stock are available.

CLIENT INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.