VOLVO CAR SERVICE AND PARTS BUSINESS



Technical Journal

TITLE: RSI cannot be turned off after software upgrade

PARTMENT:	CAR MA	ARKET:
I Service	United States	and Canada
A SA	ISSUE DATE: 2016-10-17	STATUS DATE: 2016-10-19
DESC:	Page 1	of 12
) - -	A	A 2016-10-17 DESC: Page 1

"Right first time in Time"

Attachment

File Name	File Size
USB profiles .pdf	0.3289 MB

Vehicle Type

Туре	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
256							2016-2016		0000001-0095355	201505-201616

CSC Customer Symptom Codes

Code	Description
YB	Road Sign Information (RSI)/Does not work

VST Operation Number

VST Operation Number	Description
99400-2	General reimbursement acc. to TJ/QB

DTC Diagnostic Trouble Codes



Text

DESCRIPTION:

RSI = Road Sign Information CCD = Center Console Display

If it is not possible to switch off the RSI function by deactivating the function thru RSI button and/or Speed sign Assist button (market dependent), after vehicle is upgraded to new software, then follow the instruction under service.

SERVICE:

Follow attached PDF for saving customer profiles to USB memory stick before completing global reset.

Go into CCD Settings / System / Global Reset / Reset Personal Settings, then push Reset for all profiles.

NOTE:

Failure to follow instructions to save customer profile will erase data and then need to be reset by customer.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 3872.

To view TJ attachment continue to next page. This TJ has one attachment.



Handling customer profiles

Special tools	
	951 3060 USB memory Tool number: 951 3060 Tool description: USB memory Tool boards: 39

Handling



Note! Orientation view

Preparation





Special Tool: 951 3060









Restoring









Syste Driver P	rofile		R
Profil Choos		alised setti	q
Profi Choc	Export prof	iles to USB	
Profi Choc	Profile 1		
Gue Choc	Profile 2		
Impc Copy	Profile 3		
Ехрс Сору	Yes	No	

Repeat the number of times stated





Warning!

Wait for the time specified.

Remove the Special Tool.



Special Tool: 951 3060



















Repeat the number of times stated



Warning!

Wait for the time specified.

Remove the Special Tool.