

Service Bulletin

File in Section:

Bulletin No.: 16-NA-194

Date: June, 2016

TECHNICAL

Subject: Check Engine Light Illuminated After Using Manual Paddle Shift Levers, DTC P16F3 Set

Brand	: Model:	Model Year:		VIN:		Engine:	Transmission:
Brand:	. Woder.	from	to	from	to		
Cadilla	c ATS, CTS						Equipped with
Chevrole	et Camaro	2016	2016			Equipped with 3.6L Engine (RPO LGX)	Automatic Transmission (RPOs M5T, M5N)

Involved Region or Country	North America and China
Condition	Some customers may comment on the check engine light being illuminated. In some cases the check engine light may have illuminated after using the manual paddle shift levers. A Technician may find DTC P16F3 set or stored in history.
Cause	This condition may be caused by software anomaly.

Correction

Update the transmission control module (TCM) with the latest software available from TIS2WEB.

Service Procedure

Refer to K71 Transmission Control Module: Programming and Setup (8L45/90) in SI.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2810175	Transmission Control Module Reprogramming with SPS	Use Published Labor Operation Time

Version	1
Modified	